

Appendix A | Summary of Changes

The table below shows significant program and policy changes for Fiscal Year 2022-2023. The effective date for all revisions is July 1, 2022.

Section	Topic	Revision
2.1	Program Management	Addition (new) WPN 22-4 for Work Quality and Standard Work Specifications
2.1.6	Quality Control System	Quality Work Requirements, WPN 22-2
2.1.6	Quality Control System	Threshold Increased for estimated job cost review, \$15,000/unit and \$5,000 for Health and Safety
3.3	Building Eligibility	Re-weatherization for units weatherized on or before 7/1/2006, Customer must have eligible application, all fund sources (PB, LIHEAP, DOE)
3.6	Deferral of Weatherization Services	DOE Weatherization Readiness Funds, PB, LIHEAP, Health & Safety Threshold review \$5,000 New WPN 22-7 replaces WPN 17-7
3.9.1	Multi-family (5= units)	Clarification – See Section 8.7.3.2
5.2	Disallowed Costs	Production and Quality Bonuses or incentive pay
5.3 (14)	Allowed Costs	Recruitment, Retention, Referral Agency Developed Bonus Plan, optional. Two percent of contract total may be allocated to be paid using PB funds
5.3.4	Health and Safety	H&S review threshold increased to \$5,000
5.3.7.2	Contractor training	Only PB T&TA funds are allowed to reimburse contractors for training expenses
5.3.8	Braiding funds	Terminology changed from Blending funds to Braiding funds to coincide with DOE language

Section	Topic	Revision
5.3.9	Average Cost Per Unit (ACPU)	\$8,009 for DOE funded jobs
8.4.2.1 (4)	Health and Safety	Threshold for H&S review increased to \$5,000
8.8.5	Clothes Washer Replacement and Removal - new measure	Optional: Clothes washer replacement to high efficiency Energy Star. Must replace a non-efficient model. 1-4 units and mobile homes
8.10	Weatherization Readiness Funds (WRF)	ZZ Repair codes, all fund sources, max of \$6,000 per fund source. Use of DOE WRF requires a deferral status in the System, 1-4 units only, no mobile homes
9.1	General Health and Safety	Threshold for H&S review increased to \$5,000 WPN 22-7
9.2	Radon and Weatherization	Air-tight seal on sump pits, See Field Guide for more details